INDEX

α
see Type I decision error
β
see Type II decision error
91b material 3-5
A_{min}
area of elevated activity D-23
action level 2-14, 27; 4-34, 35; 7-3; D-6, 8, 9, 15, 16
activity 2-3; 3-11
activity concentration 4-1, 6
distribution 2-29, 30; 6-33, 34
ratios 4-4, 5
gross activity 4-8
units of activity 2-14; 4-1
see elevated activity
air 3-19; 5-10, 14, 18; 6-11, 13, 55 to 60; 7-13, 16, 27; App. M
ALARA 2-5; 5-52; 8-21, 27; C-8 to 10
alpha (α) radiation 4-6, 7; 7-15
analysis 7-22
detection sensitivity
direct measurement 6-32 to 37
scanning 2-14; 5-48; 6-47 to 49
detectors 6-15 to 17, 20
attenuation 4-23, 25
measurement 5-12, 13; 6-13, 14
radon 6-55 to 59
alternative hypothesis 2-39; 5-25; 8-11, 17
area
evaluation & HSA 3-11
classification 2-4, 5, 17, 28; 4-11
contaminated 2-3
land 4-26
reference coordinate system 4-27
scanning 2-31; 5-46 to 48
site 4-17
site diagram 3-21
structures 4-23, 25
survey unit 2-4; 4-15
area of elevated activity 2-3, 4, 27, 28, 30; 5-35 to 39; 6-42 to 45; 8-22, 23, 27
demonstrating compliance 2-27
determining data points 5-35
flagging 5-44
investigation level 5-44 to 46
final status survey design 2-29, 32; 5-46 to 52
area factor 2-27; 5-36 to 39; 8-16, 22, 24
arithmetic mean
see mean
arithmetic standard deviation
see standard deviation
background (radiation)
activity 5-10, 11
decommissioning 4-13
detection sensitivity 6-37, 39 to 49
ground water 5-13
indistinguishable from 2-39
samples 5-10, 11; 7-2, 5
statistical tests 2-26; 4-9; 5-28
see background reference area
background reference area 2-6, 28; 4-13 to 16; 7-5; 8-3 to 11, 17 to 21; A-5
background radiation 4-13
data points 5-25 to 31
P_r 5-27
relative shift
WRS test 5-26
survey 5-1, 2, 10
Becquerel (Bq)
see conversion table
beta (β) radiation 4-6
analysis 7-21, 22
detection sensitivity
direct measurement 6-32 to 37
scanning 2-14; 5-48; 6-37 to 47
detectors 6-15 to 17, 21
attenuation 4-23, 25
measurement 5-12, 13
radon 6-55, 58, 59
bias 2-11; 4-32 to 38
field measurements 6-4 to 6
laboratory measurements 7-4, 5

biased sample measurement
see judgement measurement
byproduct material C-15, 16
byproducts 3-5
calibration 4-17; 6-20 to 28; 7-4, 13; 9-5, 6
CEDE (committed effective dose equivalent) 2-2
CERCLA 2-22, 39; 3-1, 2; 5-1, 7
compared to MARSSIM App. F
Chain of Custody 5-3, 17; 7-23 to 25; 9-8
characterization survey 2-15, 16, 22, 23; 3-24; 4-21; 5-7 to 17; A-17
checklist 5-16, 17
DCGLs 4-4
checklist(s)
see survey checklist
Class 1 area 2-5; 4-11; 5-48; 8-24, 25
investigation level 5-45
scanning 2-32; 5-46
Class 2 area 2-5; 4-12; 5-49; 8-24
investigation level 5-45
scanning 2-32; 5-47
Class 3 area 2-5; 4-12; 5-49
investigation level 5-45
scanning 2-33; 5-48
classification 2-4, 10, 17, 28; 3-1, 12, 22; 4-11; 5-46 to 51; 7-7; 8-1, 2, 15, 16, 22, 24, 27; A-5; N-16
areas 2-5
HSA/scoping 2-23
see Class 1, 2, and 3 area
cleanup 1-1, 4; 5-18, 19
regulations 1-3
release criterion 2-2
cleanup standard 2-2
cleanup (survey) unit
see survey unit
coefficient of variation 5-26
comparability 2-11; 6-6; 7-6, 12; N-12 to 15
completeness 2-11; 6-6, 7; 7-6, 7; N-14 to 16
computer code
DEFT D-20, 21
ELIPGRID D-23
RESRAD 5-36
RESRAD-BUILD 5-36
conceptual site model 3-21, 22; 4-21; 5-8, 47; 7-11, 13, 15; A-10
confidence interval 6-53 to 55
alternate null hypothesis 2-36
confirmatory survey
survey design 5-21
see final status survey
contamination 1-1, 2, 3, 6
characterization survey 5-7 to 15
classification 2-4, 5, 28; 3-3; 4-11
DCGLs 2-2, 3; 4-3
decommissioning criteria 5-25
field measurements 6-5, 6
final status survey 5-25 to 52
HSA 2-22
historical data 3-7, 10
reconnaissance 3-9
identifying 3-11
in soil 3-13, 14
in water 3-15, 17
in structures 3-20
in air 3-19
remedial action 2-23; 5-18, 19
sampling 7-11 to 16; App. M
surrogate measurements 4-4
see area of elevated activity
see impacted area
control chart 4-33, 37; 6-5, 7, 8
corrective action 2-23; 6-28; 7-11; 9-8, 9
bias N-10
comparability N-15
completeness N-16
precision N-9
representativeness N-13

criterion
alternate hypothesis 2-39
compliance 2-25
DCGLs 4-3
FSS 2-24
measurement 6-1
QC 4-32 to 38
release criterion 1-1 to 3; 3-24
statistical tests 2-22, 34
null hypothesis 2-9
critical level (L_c) 6-32 to 37
critical value 8-12, 13, 15, 18, 21; A-18; D-16, 17
curie (Ci)
see conversion table
data
conversion 6-28 to 31
data interpretation checklist 8-27
distribution 8-4, 5
number of points needed 2-10
EMC 5-35 to 39
Sign test 5-31 to 35
WRS test 5-25 to 31
preliminary review (DQA) E-3
review N-5
skewness 8-5
spatial dependency 8-4
see mean, median, standard deviation
see posting plot
see ranked data
see stem and leaf display
Data Life Cycle 2-6 to 12; 4-35; 5-46; 9-2, 3, 5
figure 2-7
steps:
1. planning 2-8; App. D
2. implementation 2-11
3. assessment 2-11; App. E
4. decision making 2-7
table 2-16

Data Quality Assessment (DQA) 1-4; 2-6; 5-46; 8-1, 2; 9-2, 5; App. E
assessment phase 2-8, 11; App. E
historical data 3-7

Data Quality Objectives (DQOs) 1-3, 4; 2-7, 9; 4-4, 19; 5-2, 8, 21, 52; 6-2; 7-1, 2; 8-1, 2; 9-2, 7, 8; App.D
DQO Process 2-10; App. D
iterations (figure) D-3
state problem D-4
identify decision D-5
inputs D-5, 6
study boundaries D-6 to 8
develop decision rule D-8 to 13
decision errors D-13 to 28
optimize design D-28, 29
HSA 3-2
Planning 2-9
preliminary review (DQA) E-1
measurement uncertainty 6-50
QAPP 9-2, 3
data quality indicators 2-11; 6-3, 7; 7-2, 7; 9-9; N-6 to 18
Derived Concentration Guideline Level (DCGL) 2-2, 11, 33; 4-3 to 11; 6-1, 2, 7, 19, 32, 50; 7-2, 7, 9; 8-2, 6, 11, 22, 26; 9-5
$DCGL_W$ 2-3; A-2; D-9
$DCGL_{EMC}$ 2-3
HSA 3-1, 12
gross activity 4-8
sampling 7-2, 7, 9
surveys 5-1
decay
see radioactive decay
decision error D-13 to 17, 20 to 22, 26 to 29; N-17
error chart D-27
false positive D-14, 21, 26
see Type I error
false negative D-15, 20
see Type II error
feasibility trials
DEFT D-20, 21
specifying limits D-15
table D-15

decision maker 2-6; 4-14; 5-46; 6-27; 7-2, 18; 9-8
- alternate methods 2-32
- estimating uncertainty 2-11
- DQOs 3-2; 6-2

decision rule 1-2; 8-24
- one-sample case D-11
- power chart (example) D-25
- two-sample case D-12

decision statement 8-24; D-2, 5, 6

decommissioning 1-1; 2-3; 3-1
- Characterization Survey 2-23; 5-7, 8
- criteria 4-1
- documentation 5-52
- simplified procedure App. B
- site identification 2-16
- site investigation 4-1

delta (δ) 5-26 to 35; 8-12 to 15, 19, 23; A-11, 19; D-10, 13, 16, 17, 20, 21

delta (Δ) 2-9, 10, 31
- *see relative shift*

detection limit
- *see minimum detectable concentration*

detector(s) Chap. 6; 9-6; App. H
- alpha
  - field survey 6-15 to 18, 20; H-5 to 10
  - laboratory 7-20, 22; H-38 to 42
- beta
  - field survey 6-15 to 18, 21; H-11 to 14
  - laboratory 7-20, 21; H-43 to 45
- calibration 6-20 to 28
- *in situ* spectrometry 6-11, 12
- gamma
  - field survey 6-15 to 18, 22; H-15 to 24
  - laboratory 7-20, 21; H-46 to 48
  - low energy H-31 to 33
- radon 6-57; H-25 to 30
- sensitivity 6-31 to 49
- X-ray H-31 to 33

direct measurement 2-4; 4-17; Chap. 6
- background 6-7, 35
- description 6-10 to 13
- detectors 6-15 to 22; App. H
- instruments 4-16, 6-15 to 28
- methods 4-17
- QC 4-32 to 38
- radon 6-55 to 60
- replicates 6-3
- sensitivity 6-31 to 49
- surveys 5-45 to 51

distribution coefficient (K_d) 3-19

documentation N-2 to 4

dose equivalent (dose) 1-1, 3; 2-1, 2
- DCGL 2-3; 5-36 to 38
- release criterion 2-2

effective probe area 6-29, 37

elevated area
- *see area of elevated activity*

elevated measurement
- *see area of elevated activity*

Elevated Measurement Comparison (EMC) 2-3, 27, 32; 8-5, 9, 17, 18, 21 to 23
- $DCGL_{EMC}$ 2-3, 27
- number of data points 5-35 to 39
  - example 5-39; A-16
- *see area of elevated activity*

exposure pathway model 2-2, 15, 27; 5-38, 44; 8-9, 23

exposure rate 4-20; 5-9 to 11, 17, 51

field sampling plan 2-6; 9-3

field survey equipment H-5 to 37

final status survey 2-4, 24, 32; 3-24; 5-21 to 55; 8-1, 6, 10, 23 to 25; 9-5
- checklist 5-53 to 55
- classification 2-28; 4-11
- compliance 2-25
- DCGL 4-3
- example App. A
- figure 2-21

final status survey (continued)
health and safety 4-38
integrated design 2-32
investigation process 2-16
planning 2-9; 5-21 to 55
sampling 7-7 to 16; App. M
survey units 4-14
fluence rate 6-11, 12, 44
frequency plot 8-4, 5
gamma (γ) radiation
analysis 7-21
detection sensitivity 6-31
direct measurement 6-32 to 37
scanning 6-37 to 47
detectors 6-15 to 18, 22; 7-20, 21; H-15 to 24, 46 to 48
measurement 4-16
radon 6-55, 57, 60
scanning 6-14
spectrometry 4-16
surface measurement 6-11, 12
graded approach 1-5; 2-4, 5, 8; 3-1; 6-8; 8-1; 9-2, 3, 5
graphical data review 8-4; E-3
see frequency plot
see posting plot
see stem and leaf display
gray region 2-9, 31; 5-25 to 27, 32, 33; 6-7; 7-7, 8 to 12, 14, 19; D-16, 17, 20 to 22, 26, 28
example A-7, 11
see decision error
see lower bound (LBGR)
grid 2-31; 4-27 to 31; 5-3, 16, 40 to 43; 7-7
example A-7, 13, 14, 15
positioning systems 6-61, 62
random start example 5-40, 41; A-14
reference coordinate system 2-23; 4-27; 6-61, 66
example(s) 4-28, 29, 30
grid (continued)
sample/scan 2-32; 5-40
spacing 5-42
triangular grid 5-40 to 43
figure 5-43
half-life ($t_{1/2}$) 1-5; 4-6; 6-55; A-1; B-1
histogram
see frequency plot
see stem and leaf display
Historical Site Assessment (HSA) 1-3, 4; 2-16, 22; Chap. 3; 5-1, 16, 39; 6-14; 7-12; 8-9; A-1
data sources App. G
figure 2-18
information sources App. G
survey planning 4-11
hot measurement
see area of elevated activity
hot spot
see area of elevated activity
hypothesis 2-26; 8-8, 12, 18
alternative hypothesis 2-39; D-14, 15
null hypothesis 2-9, 26; 8-11, 15, 17, 23; D-14, 15
statistical testing 1-3; 2-13, 26
approach explained 2-26
Sign test 2-28; 8-11
WRS test 2-28; 8-17
impacted area 2-4
classification 4-11
DQO 3-2
HSA 2-23; Chap. 3
non-impacted 2-4
Scoping Survey 2-23
site diagram 3-23
survey design 2-25
see *residual radioactivity*
indistinguishable from background 2-39; D-19
infiltration rate 3-14, 16, 18
inventory 3-8; 4-26

investigation level 2-2, 32; 4-1; 5-18, 44 to 46; 6-14, 15; 8-9, 17, 21
example (table) 5-45
scanning 6-3
survey strategy 5-46
see release criterion
see action level
judgment measurement 2-22, 23, 30, 33; 5-2, 3, 44, 48, 51, 55
karst terrain 3-19
laboratory equipment 4-16; H-38 to 48
less-than data 2-13
license 2-16; 3-4, 5, 7, 8; 7-11
license termination
see *decommissioning*
lower bound of the gray region (LBGR) 2-9, 31; 5-25 to 27, 31 to 33; 6-7; 7-7; 8-12, 13, 15, 19; D-17, 20, 21, 28; N-18
example A-11
see gray region
m (number of data points in the reference area) 5-29, 39, 42; 8-18, 21
mean 2-27, 28; 4-33; 5-49, 50; 8-2, 3, 5 to 7, 12, 13, 15; D-9
of data (example) 8-3
measurement techniques 1-2, 4; 2-4; 3-7; 4-16, 17; 7-20 to 22
median 2-28; 5-27, 32, 45; 8-2, 3, 5 to 7, 12, 13, 15; D-9
minimum detectable concentration (MDC) 2-10, 34; 4-16, 17, 34, 35; 5-36, 37, 48; 6-31 to 49; 8-15, 18, 22; 9-7 to 9
direct measurement 6-32 to 37
elevated activity 5-39
reporting 2-13
scan 6-37 to 49
minimum detectable count rate (MDCR) 6-40 to 45
missing or unusable data 5-29, 31, 33, 35
model(s)
conceptual site model 3-3, 22; 5-8, 47
defining study boundaries D-6, 7
exposure pathway 1-4; 2-2, 15, 27; 6-10, 28
area factor (example) 5-36
determining DCGLs 4-3, 6
N (number of data points) 2-10; 5-25 to 39; 8-12, 13, 15, 18
QC measurements 4-32 to 38
Sign test 5-31 to 35
example 5-33, 35; B-2
table 5-34
WRS test 5-25 to 31
example 5-29, 31; A-11; B-2
table 5-30
n (number of data points in survey unit) 5-29, 38, 42; 8-18, 21
NARM 3-4
naturally occurring radionuclides 1-4; 3-3; 6-5; 7-5
non-impacted area 2-4
background (reference area) 4-13
classification 2-28; 4-11
DQO 3-2
HSA 2-17; 3-10 to 12
survey design 2-31

nonparametric test 2-26; 4-10, 11; 5-25; 8-6, 7, 22, 24, 25
- alternate methods 2-34 to 38
- one-sample test 2-28; 5-31; 8-11 to 16; D-10
- two-sample test 2-28; 5-25; 8-17 to 21; D-10
- *see Sign test*
- see *Wilcoxon Rank Sum test*
- *see Wilcoxon Signed Rank test*

normal (gaussian) distribution 2-28; 5-45; 6-54, 55; 8-6; I-1

one-sample test 2-28; 5-25, 31 to 35
- *see Sign test*

outlier 9-7

P_r 5-27, 28; I-27, 28

performance evaluation 4-35, 37; 6-4, 9; 7-4, 10

physical probe area 6-29, 30, 38, 48

posting plot 2-27; 8-4, 8, 13

power (1-β) 2-31, 34; 4-26; 5-27, 29, 33, 54; 6-15, 17; 8-2, 3, 5, 6, 8, 12, 15, 23, 27; D-15, 17 to 19, 25, 26
- Sign test I-25, 26
- WRS test I-27 to 29
- chart D-25
- power curve I-26, 29
- example A-7, 9, 11, 12

precision 2-11; 4-32 to 38; 9-9; N-6 to 8
- global positioning system 6-61, 62
- QC measurements 4-35, 37; 6-3, 4; 7-3, 4

probe area 6-20, 21, 24, 29, 30, 36, 37, 38, 43, 48

quality 2-6, 8, 9
- assessment data 2-11
- data quality needs 2-8
- HSA data 3-10
- professional judgment 3-22

quality assurance (QA) 2-6; 4-32; 8-1, 2, 4, 7; 9-1 to 4
- review of HSA 3-25
- document comparison tables App. K

Quality Assurance Project Plan (QAPP) 2-6; 4-31, 32; 5-5, 54, 55; 7-9; 9-2, 3, 6

quality control (QC) 2-6; 8-2; 9-1, 5, 7
- field measurement control 6-3 to 8
- laboratory control 7-2 to 7
- number of measurements 4-32 to 38

quality system 9-1 to 4

Quantile plot 8-4, 7, 8, 13; I-18 to 21

Quantile-Quantile plot A-16, 17; I-22 to 24

R 5-29, 31, 33, 35

R_A D-23

radiation program managers
- list by region App. L

radiation survey 1-1, 4;4-4, 21
- data life cycle 2-16
- HSA 2-22; 3-1, 8
- scoping survey 2-22; 5-1 to 6
- characterization survey 2-23; 5-7 to 17
- remedial action support survey 2-23; 5-18 to 20
- final status survey 2-24; 5-21 to 55
- planning 2-8 to 11; Chap. 4; Chap. 5
- process 2-14, 17 to 21

radioactive decay 3-12; 7-18, 20
- decay chain 4-6, 7
- half-life 4-5
- radon 6-55, 58, 59
- scan MDC 6-44 to 46
- survey design 5-5, 8, 16

radioactivity
- *see residual radioactivity*

radiological survey
- *see radiation survey*

radionuclide 2-2, 5
- compliance/dose 2-25
- *see unity rule*

radon 3-20; 5-14; 6-55 to 60
random uncertainty 2-14; 6-50 to 52
ranked data I-22
interpolated ranks I-23
RCRA 2-22, 23, 39; 3-1; 5-1, 7
compared to MARSSIM App. F
reference coordinate system
see grid
regulations & requirements App. C
DOD C-15 to 20
DOE C-4 to 12
EPA C-1 to 4
NRC C-12 to 15
States C-20, 21
relative shift (Δ/σ) 5-26 to 35, 40, 42; 8-12 to 15, 19; D-17, 20
calculate 5-26, 5-32
example 5-29, 5-33; A-11, 19
DQO process 2-9, 10, 31
number of data points 5-28, 33
P_r 5-27
Sign p 5-32
tables
N (Sign test) 5-34
N/2 (WRS test) 5-30
P_r 5-28
Sign p 5-32
release criterion 1-1, 2, 5; 2-2
alternate null hypothesis 2-39
compliance 2-25
DCGLs 4-3
final status survey 2-24
null hypothesis 2-9, 26
statistical tests 2-25
survey planning 5-1
rem (radiation equivalent man)
see conversion table
remedial action support survey 2-15, 23; 5-18 to 20; 6-12; 8-25
checklist 5-20
figure 2-20
table 2-16
remediation 1-1, 3, 4; 8-9, 11
see remedial action support survey
removable activity 5-17, 52; 6-20, 21
see surface contamination
removal 2-5; 5-2
criteria 2-23; App. F
of structures/equipment 4-24 to 26
Superfund App. F
HSA 3-1
scoping survey 5-2
replicate 4-35, 37
sample 7-3
measurement 6-3
representativeness 2-11, 24; 4-34; 6-6; 7-3; N-12, 13
reproducibility 4-27; 6-61
residual radioactivity 2-3, 26; 3-24; 4-1, 24
analytical procedures 7-17 to 23
characterization surveys
land areas 5-11
structures 5-10
final status survey
land areas 5-40, 50, 51
structures 5-44, 48 to 50
remedial action design 5-18
see surface contamination
restricted use 1-1; 5-7
see unrestricted release
robust 2-35, 37; 8-6
s 5-45, 49; 8-2
S+ 8-12 to 16
see test statistic
sample(s) 2-4
alternate survey design 2-33
background 4-13
blanks 7-5
Chain of Custody 7-23 to 25
characterization
land 5-11
structures 5-10
confirmation/verification 2-25
criteria 4-19, 21
DCGLs 4-4

sample(s) (continued)
documentation 5-52
final status survey
locations 5-40 to 44
number of data points 5-25 to 39
matrix spikes 7-4
packing/transport 7-25 to 28
preservation of 7-16, 17
QC 4-32 to 38
remedial action 5-19
sampling 2-4
scoping 5-2, 3
soil 7-11 to 14
surrogate 4-4
water & sediments 5-12, 13
Sampling and Analysis Plan 2-6; 9-3
scanning 2-4; 4-17
alpha 6-14
alpha scanning sensitivity
equations - derivations App. J
beta 6-15
demonstrating compliance 2-31
detectors 6-15 to 18, 20 to 22, 57; App. H
elevated activity 2-29
gamma 6-14
MDCs 6-37 to 49
pattern (example) A-6
sensitivity 6-37 to 49
survey techniques 4-17; 6-13 to 15
scanning surveys
scoping 5-3, 6
characterization
land areas 5-11
structures 5-10
remedial action 5-19
final status
Class 1 areas 2-32; 5-46
Class 2 areas 2-32; 5-47
Class 3 areas 2-33; 5-48
scoping survey 2-15, 22; 5-1 to 6
area classification 4-11
checklist 5-5, 6
figure 2-19
HSA & planning 3-1, 2
table 2-16
sealed source
final status survey example App. B
sigma (σ)
see standard deviation
Sievert (Sv)
see conversion table
Sign test 2-3, 27, 28; 5-25; 8-11 to 16
applying test 8-12
example(s) 8-12, 14
hypothesis 8-11
number of data points 5-31 to 35
example 5-33, 35
power I-25, 26
Sign p 5-32
site(s) Chap. 1
clearing for access 4-24
decommissioning 4-1
definition 2-3
historical assessment Chap. 3
identification 2-16; 3-4
investigation process 2-14
site preparation 4-22
site reconnaissance 3-9
identify contamination 3-13
site model 3-22
smear (swipe)
see removable activity
soil 3-13 to 15
analysis 7-17 to 23
background 4-13
sampling 7-11 to 14
surveys 5-33, 9 to 11, 19, 33, 47, 50, 51
survey coverage 2-32; 5-47
source term 4-21
split
regulatory verification 2-25
sample 4-35; 7-3, 14
standard deviation 2-9, 31; 4-16; 5-26, 29, 31, 32, 45, 49; 8-2, 10, 12 to 15, 19, 23; A-11, 19; N-17
standard operating procedure (SOP) 6-3, 51; 7-9, 19, 25

statistical tests 2-25; 4-11; 5-25; Chap. 8; App. I
- alternate methods 2-34 to 38
- documenting 8-25, 26
- interpreting results 8-21 to 25
- selecting a test 8-6, 7; E-4
- summary (table) 8-9
- verify assumptions 8-7, 8; E-4

stem & leaf display 8-5, 7; I-17, 18

structures 3-20
- access 4-25
- HSA site plots 3-8
- measurements 4-20
- reference coordinate system 4-27 to 31
- surface activity 5-10
- surveys 5-7 to 10, 46, 47
- survey coverage 5-47
- survey example App. A
- survey unit 2-4; 4-14, 15
- WRS test (example)
  - Class 1 8-21, App. A
  - Class 2 8-19

Student's t test 2-35, 37

subsurface soil (sample) 1-9; 4-24
- characterization survey 5-9, 5, 11
- HSA 3-11, 13, 14
- sampling 7-16; App. M

surface contamination 1-3, 4
- detectors
  - alpha 6-20
  - beta 6-21
  - gamma 6-22
- direct measurements 6-10 to 13
- identification 3-12
- *in situ* spectrometry 6-11, 12
- land areas 4-24
- scanning 6-13 to 15
- soil 3-14
- structures 4-23; 5-10
- surface activity DCGLs 4-4
- surrogates/DCGLs 4-4

surface soil 1-3, 1-4; 3-13
- background 4-13
- sampling 7-9, 12 to 14, 16, 17, 21; App. M

surrogate measurements 4-4 to 7; 5-12; 6-14; 9-7

survey
- approach Chap. 1
- DCGLs 4-3
- decommissioning criteria 4-1
- DQOs 2-9 to 11
- field measurements Chap. 6
- instruments/technique 4-16; App. H
- overview Chap. 2
- planning 2-8 to 11; Chap. 5
- QAPP 2-6
- sampling/preparation Chap. 7, App. M
- simplified procedure App. B
- site investigation process 2-14
- statistical tests 2-25; Chap. 8; App. I
- survey considerations Chap. 4
- using MARSSIM 1-6; Roadmap
- *see characterization* *5-7 to 16*
- *see final status* *5-20 to 53*
- *see HSA* *Chapter 3*
- *see remedial action* *5-17 to 19*
- *see scoping* *5-1 to 6*
- *see Data Life Cycle*
- *see survey unit*

survey checklist
- characterization 5-16, 17
- final status 5-53 to 55
- remedial action 5-20
- scoping 5-5, 6
- statistical tests 8-27

survey plan 1-5; 2-6; 5-54; 7-8, 18
- alternate designs 2-33 to 40
- design Chap. 4; Chap. 5
- DQOs 2-9; 3-3
- optimizing survey 2-30

survey unit 2-4; 4-14; 7-5; 9-6, 8; N-16
- area 4-15
- characterization 5-9 to 5-11
- characterize/DQOs 2-9
- classification 2-28; 4-11, 12
- classify/flowchart 2-17
- elevated activity 2-27
- HSA 3-1, 2, 4
- identifying 4-14
- investigation level 5-44 to 46
- statistics & final status survey 5-21 to 55
- uniform contamination 2-28

surveyor(s) 4-22, 31; 6-24, 37, 38, 40 to 48
selecting 6-8, 9
systematic uncertainty 6-50 to 52
systematic grid 2-31, 32; 5-46; 6-7, 12; 8-19, 22
test statistic 8-12, 13, 15; D-16 to 19
example (S+) 8-12 to 16
example (W_r, W_s) 8-18
see *critical level*
total effective dose equivalent (TEDE) 2-2
triangular sampling grid 5-35, 36, 42 to 44; 8-4, 13, 16, 19
see systematic grid
two-sample test 2-28; 5-25 to 31; D-10
alternate methods 2-37, 38
nonparametric test 4-9 to 11
see Wilcoxon Ranked Sign test
Type I decision error 5-25 to 35; 6-33, 34; 8-8, 10, 13 to 15, 18, 19, 21; 9-8, 9; D-14 to 17, 21, 26, 28
DQOs 2-9, 10, 31
examples 8-10; A-7, 11, 18; B-2
Type II decision error 5-25 to 35; 6-33, 34; 8-8, 10, 12 to 15, 19; 9-8, 9; D-14 to 18, 20, 21, 26, 28
DQOs 2-9, 10, 31
examples 8-10; A-7, 11; B-2
uncertainty 1-2; 2-25; 5-11, 14, 26, 29, 33, 35, 45, 46; 6-49 to 55; 7-3, 4, 8, 21; 8-17, 18; 9-7, 9
uncertainty (continued)
confidence intervals 6-53 to 55
decision making 2-7
DCGL 2-33
estimating 2-11
measurement 6-49 to 55
MDC 4-17
propagation 6-52, 53
QC 4-32 to 38
reporting 2-14
statistical counting 6-52
systematic/random 6-50 to 52
unity rule (mixture rule) 2-27; 4-8; 5-38; 8-21, 23
adjusting DCGLs 4-8 to 4-10
unrestricted release 3-22
validation 2-8, 11; 7-9; 9-2, 5, 7, 8; App. N
verification 2-15, 25; 5-21; 6-32; 7-9; 8-8; 9-2, 4 to 7
W_r 8-18
see test statistic
W_s 8-18
see test statistic
Wilcoxon Rank Sum (WRS) test 2-28; 5-25 to 31; 8-17 to 21
adjusted data 8-20
example 8-19, 21; A-10, 11, 18, 19
applying the test 8-18
Class 1 example 8-21
Class 2 example 8-19
power I-27 to 29
spreadsheet formulas I-30
see two-sample test
working level 6-56